



IMPORTANT:
The AFP will need to be recalibrated during replacement to ensure proper operation.

